For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2023–07–01 Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.): Amendment 39–22402; Docket No. FAA–2023–0658; Project Identifier MCAI–2023–00315–T.

(a) Effective Date

This airworthiness directive (AD) is effective April 19, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Canada Limited Partnership (Type Certificate previously held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Model BD–500–1A10 and BD–500–1A11 airplanes, certificated in any category, as identified in Transport Canada Emergency AD CF–2023–12, dated February 23, 2023 (Transport Canada Emergency AD CF–2023–12).

(d) Subject

Air Transport Association (ATA) of America Code 72, Turbine/turboprop engine.

(e) Unsafe Condition

This AD was prompted by several unscheduled PW1500G engine removals due to crew alerting system (CAS) message L/R ENGINE FAULT with associated INFO message OIL DEBRIS ABOVE LIMIT being displayed, high vibration, or debris found on the magnetic chip collector of bearing compartment No. 3 (BC3). The FAA is issuing this AD to prevent a No. 3 bearing failure. The unsafe condition, if not addressed, could result in unrecoverable engine failure or power loss for both engines

and consequent reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Transport Canada Emergency AD CF–2023–12.

(h) Exception to Transport Canada Emergency AD CF-2023-12

Where Transport Canada Emergency AD CF-2023-12 refers to its effective date, this AD requires using the effective date of this AD.

(i) Additional AD Provisions

The following provisions also apply to this AD:

- (1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.
- (2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada; or Airbus Canada Limited Partnership's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Additional Information

For more information about this AD, contact Joseph Catanzaro, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7366; email 9-avs-nyacocos@faa.gov.

(k) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.
- (i) Transport Canada Emergency AD CF–2023–12, dated February 23, 2023.
- (ii) [Reserved]
- (3) For Transport Canada Emergency AD CF–2023–12, contact Transport Canada,

Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888– 663–3639; email *AD-CN@tc.gc.ca*; website *tc.canada.ca/en/aviation*.

- (4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.
- (5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibrlocations.html.

Issued on March 28, 2023.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–06989 Filed 3–30–23; 4:15 pm]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2022-1454; Airspace Docket No. 21-AWP-56]

RIN 2120-AA66

Amendment of Class E Airspace; Boswell Airport, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action modifies the Class E airspace extending upward from 700 feet above the surface at Boswell Airport, CA. It reduces the radius, establishes an extension to the north, modifies the extension to the south, and it makes several administrative modifications to update the airport's legal description. These actions will support the safety and management of instrument flight rule (IFR) operations at the airport.

DATES: Effective date 0901 UTC, June 15, 2023. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: A copy of the Notice of Proposed Rulemaking (NPRM), all comments received, this final rule, and all background material may be viewed online at www.regulations.gov using the FAA Docket number. Electronic retrieval help and guidelines are available on the website. It is available 24 hours each day, 365 days each year.

FAA Order JO 7400.11G, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at www.faa.gov/air_traffic/publications/. You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

FOR FURTHER INFORMATION CONTACT:

Keith Adams, Federal Aviation Administration, Western Service Center, Operations Support Group, 2200 S 216th Street, Des Moines, WA 98198; telephone (206) 231–2428.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority, as it modifies the Class E airspace at Boswell Airport, CA, to support IFR operations at the airport.

History

The FAA published a notice of proposed rulemaking for Docket No. FAA–2022–1454 in the **Federal Register** (87 FR 76592; December 15, 2022), modifying Class E airspace extending upward from 700 feet above the surface at Boswell Airport, CA. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Incorporation by Reference

Class E5 airspace is published in paragraph 6005 of FAA Order JO 7400.11, Airspace Designations and Reporting Points, which is incorporated by reference in 14 CFR 71.1 on an annual basis. This document amends the current version of that order, FAA Order JO 7400.11G, dated August 19, 2022 and effective September 15, 2022. FAA Order JO 7400.11G is publicly available as listed in the ADDRESSES section of this document. These

amendments will be published in the next update to FAA Order JO 7400.11.

FAA Order JO 7400.11G lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This action amends 14 CFR part 71 by modifying the Class E airspace extending upward from 700 feet above the surface at Boswell Airport, CA. The 6.6-mile radius airspace area encircling the airport is reduced to a 2.4-mile radius, as circling maneuvers are not authorized at the airport. The southeast extension of the airport is widened, shortened, and re-aligned to be within 2.1 miles either side of the 148° bearing from the airport, extending from the 2.4mile radius to 6.7 miles southeast of the airport to better contain arriving IFR operations below 1,500 feet above the surface and departing IFR operations until they reach 1,200 feet above the surface. Additionally, a northern extension was added to the airspace description, which is 2.4 miles either side of the 346° bearing from the airport, extending from the 2.4-mile radius to 7.6 miles north of the airport to better contain arriving IFR operations below 1,500 feet above the surface and departing IFR operations until they reach 1,200 feet above the surface.

Finally, this action makes several administrative modifications to the airport's legal description. The airport name in line one of the text header is corrected from "Salyer Farms" to read "Corcoran, CA." The airport name in line two of the text header is corrected from "Salyer Farms Airport" to "Boswell Airport." Moreover, reference to the Salyer Farms nondirectional beacon has been removed from line 4 of the text header, as it is not needed to describe the airspace. The geographic coordinates for the airport are updated to match the FAA's database.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant

economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5–6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order JO 7400.11G, Airspace Designations and Reporting Points, dated August 19, 2022, and effective September 15, 2022, is amended as follows:

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.

AWP CA E5 Corcoran, CA [Amended]

Boswell Airport, CA

(Lat. 36°05′19" N, long. 119°32′30" W)

That airspace extending upward from 700 feet above the surface within a 2.4-mile radius of the airport, and within 2.1 miles each side of the 148° bearing from the airport extending from the 2.4-mile radius to 6.7 miles southeast of the airport, and within 2.4 miles each side of the 346° bearing from the airport extending from the 2.4-mile radius to 7.6 miles north of the airport.

Issued in Des Moines, Washington, on March 28, 2023.

B.G. Chew,

Group Manager, Operations Support Group, Western Service Center.

[FR Doc. 2023–06890 Filed 4–3–23; 8:45 am]

BILLING CODE 4910-13-P